



# Moritz Manufacturing Enterprise cc

## Core Winder

These machines have only the necessary components  
Minimum waste on these machines  
Runs a 2 ply core. Can run 4 ply with extra backstand  
Runs all kinds of different GSM paper  
Can sustain 2 machines  
Single phase  
Low maintenance costs

